HAER ND. 5-KRA.V.

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

J. Clark Salyer National Wildlife Refuge, Dam 341

HAER No. ND-4-D

Along the Souris River
Bottineau County
McHenry County
North Dakota

NOTE: Photographs were taken by Frederick L. Quivik, photographer, May 1990

ND-4-D-1	VIEW OF DAM 341, LOOKING SOUTHWEST ALONG THE CREST OF THE DAM	
ND-4-D-2	VIEW OF DAM 341, LOOKING NORTHEAST ALONG THE CREST FROM THE EAST END OF THE SPILLWAY TOWARD THE OUTLET WORKS, SHOWING THE UPSTREAM FACE OF THE DAM	
ND-4-D-3	VIEW OF DAM 341, SHOWING THE DOWNSTREAM SIDE OF THE OUTLET WORKS, LOOKING SOUTHEAST	
ND-4-D-4	VIEW OF DAM 341, SHOWING DOWNSTREAM SIDE OF OUTLET WORKS FROM THE WEST SIDE, LOOKING EAST	
ND-4-D-5	VIEW OF DAM 341, SHOWING THE UPSTREAM SIDE OF OUTLET WORKS FROM THE WEST SIDE, LOOKING NORTHEAST	
ND-4-D-6	VIEW OF DAM 341, LOOKING EAST OVER THE TOP OF THE OUTLET WORKS WITH THE GATES RAISED	
ND-4-D-7	DETAIL VIEW OF HAND-OPERATED RADIAL GATE HOIST AT DAM 341, LOOKING SOUTHWEST	
ND-4-D-8	VIEW OF SPILLWAY AT DAM 341, LOOKING NORTHEAST	
ND-4-D-9	VIEW SHOWING EAST END OF SPILLWAY AT DAM 341, LOOKING NORTHEAST	
ND-4-D-10	DETAIL VIEW OF THE CONCRETE BUTTRESSING NEAR THE MIDDLE OF THE SPILLWAY AT DAM 341, LOOKING SOUTHEAST	
The following are photocopies of historic photographs. Original prints can be found in narrative reports of		

The following are photocopies of historic photographs. Original prints can be found in narrative reports of the Lower Souris Migratory Waterfowl Refuge for the 1930s, on file at the headquarters of the J. Clark Salyer National Wildlife Refuge, Upham, North Dakota.

ND-4-D-11	VIEW OF THE LOWER END OF UNIT IV. DAM 341 ON THE RIGHT

ND-4-D-12 VIEW SHOWING THE CLOSING OF THE GATES OF DAM 341 ON APRIL 15, 1936, THE DAY THEY BEGAN FLOODING THE MARSHES

J. Clark Salyer National Wildlife Refuge, Dam 341HAER No. ND-4-CIndex to Photographs (Page 2)

The following are photocopies of original construction drawings, dated July 1950, from files at the Office of the Chief Engineer, U.S. Fish and Wildlife Service Regional Office, Denver.

ND-4-D-13 REPAIRS TO DAMAGED SPILLWAY 341

ND-4-D-14 REPAIRS TO SPILLWAYS NOs. 320, 326, 332, 341

For photographs and historical information on other dams in the J. Clark Salyer National Wildlife Refuge, see HAER No. ND-4-A, Dam 320; HAER No. ND-4-B, Dam No. 326; HAER No. ND-4-C, Dam 332, and HAER No. ND-4-E, Dam 357.